

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/23/2021

Submitted Date:

07/23/2021

Document Number:

701101755

FIELD INSPECTION FORM

Loc ID 315085 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10539
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
Address: 1125 ESCALANTE DR
City: RANGELY State: CO Zip: 81648

Findings:

- 13 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Gas, UtahGasCorp	970-693-6021	inspections@utahgascorp.com	Inspection mail box

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230230	WELL	PR	07/01/2019	GW	103-07889	FOUNDATION CREEK B 7406	PR

General Comment:

COGCC Routine Inspection Report Summary
Location is in close proximity of West Douglas Creek and in a High Priority Habitat Area.
During this inspection the following compliance issues were observed:

- No battery sign at tank battery.
- Tank label is weathered and illegible.
- Weeds covering location.
- Subsidence near east side of well. Sediment movement and washing on access road.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
Lease Road:			
Type	Access		
comment:	Weeds and pothole at cattle gaurd.		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	No api# on well tag/sign		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank label is weathered and illegible.		
Corrective Action:	Comply with Rule 605.h.(2)	Date:	10/25/2021
Type	BATTERY		
Comment:	No battery sign at tank battery.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	10/30/2021
Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds covering location.		
Corrective Action:	Comply with Rule 606	Date:	08/10/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Equipment:			
Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		

Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	30 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities

Facility ID: 230230 Type: WELL API Number: 103-07889 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				Not maintained.
Compaction	Fail					Subsidence a few yard east of wellhead. Ruts on loc
		Gravel				
		Compaction				
Seeding						

Comment: [Subsidence near east side of well. Sediment movement and washing on access road.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 08/10/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101756	Inspection 701101755 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5488364