

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: electric

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment: electric motor

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 240980 Type: WELL API Number: 123-08768 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: annual bradenhead test not on record. Contact COGCC engineering.01/10/2021Corrective Action: Comply with COGCC annual bradenhead testing rules.

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On 7/15/21 at approximately 1100 I, Inspector Justin Medina conducted an on-site inspection at:
 Well Name- B C Hopkins 31-19 1-67 3
 Company Name- Fritzler resources
 API- 05-123-08768
 In Weld County Colorado.
 While there, I observed PR well
 This is a follow up inspection from document # 699502091 Corrective Actions are Delinquent
 During this inspection the following possible compliance issues were observed:
 Annual bradenhead test is not on file. Contact COGCC engineering
 Comply with COGCC annual bradenhead testing rules. 1/10/21
 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

medinaj

07/15/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402757637	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5487082
699503007	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5487071