

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/30/2021

Submitted Date:

07/30/2021

Document Number:

699503049**FIELD INSPECTION FORM**
 Loc ID 318376 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241188	WELL	PR	03/20/1995	GW	123-08976	ALEX H MILLER 1	PR

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Location inaccessible due to weeds growing on lease road. Lease road follows a canal and the edge of the canal was not visible. Other side of road has a ditch that is not visible.		
Corrective Action:	Comply with COGCC housekeeping rules.	Date:	08/30/2021

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 241188 Type: WELL API Number: 123-08976 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 07/21/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 7/30/21 at approximately 1100 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Alex H Miller 1</p> <p>Company Name- KPK</p> <p>API- 05-123-08976</p> <p>In Weld County Colorado.</p> <p>While there, I observed PR</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Location inaccessible due to weeds growing on lease road. Lease road follows a canal and the edge of the canal was not visible.</p> <p>Comply with COGCC housekeeping rules 8-30-21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	07/30/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503050	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5494655">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5494655</a>