

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402769650

Date Received:

08/03/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

TEP

Phone

970-285-9377

Email

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700703012

Inspection Date: 07/19/2021

FIR Submit Date: 07/19/2021

FIR Status: _____

Inspected Operator Information:

Company Name: GRIZZLY OPERATING LLC

Company Number: 10531

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 335440

Location Name: STRANAHAN-66S92W Number: 27NENW County: _____

Qtrqtr: NENW Sec: 27 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.505031 Longitude: -107.654823

FACILITY - API Number: 05-045- -00 Facility ID: 335440

Facility Name: STRANAHAN-66S92W Number: 27NENW

Qtrqtr: NENW Sec: 27 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.505031 Longitude: -107.654823

CORRECTIVE ACTIONS:

1 CA# 153892

Corrective Action: remove unused equipment

Date: 08/19/2021

Response: CA COMPLETED

Date of Completion: 08/03/2021

Operator
Comment:

The Colorado Air Pollution Control Division (APCD) currently requires the use of air pollution control equipment (e.g., enclosed combustor) on all produced water and condensate storage tanks with ≥ 2 tpy uncontrolled VOC emissions. TEP utilizes enclosed combustors (ECDs) to comply with this regulation. When uncontrolled emissions fall below the 2 tpy threshold, TEP will often disconnect the ECD from the tank battery. However, due to the potential of a future increase in facility emissions or a future reduction of the control threshold, TEP will often elect to leave the ECD in place. An ECD in this status is not "unused equipment", rather, it is considered to be temporarily out of service.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The corrective action has been addressed. Please see response on Corrective Actions tab.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP ENV

Date: 8/3/2021 5:35:32 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

--	--

Total Attach: 0 Files