

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402759491

Date Received:

07/26/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10396

Name of Operator: SWN PRODUCTION COMPANY LLC

Address: P.O. BOX 12359

City: SPRING State: TX Zip: 77389

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Karen Maneotis

Phone

970-620-6099

Email

karen_maneotis@swn.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202944

Inspection Date: 07/14/2021

FIR Submit Date: 07/16/2021

FIR Status: _____

Inspected Operator Information:

Company Name: SWN PRODUCTION COMPANY LLC

Company Number: 10396

Address: P.O. BOX 12359

City: SPRING State: TX Zip: 77389

LOCATION - Location ID: 423345

Location Name: Weber Number: 32-4 County: _____

Qtrqr: SW Sec: 4 Twp: 6N Range: 92W Meridian: 6
NE

Latitude: 40.501175 Longitude: -107.722908

FACILITY - API Number: 05-081- -00 Facility ID: 423345

Facility Name: Weber Number: 32-4

Qtrqr: SW Sec: 4 Twp: 6N Range: 92W Meridian: 6
NE

Latitude: 40.501175 Longitude: -107.722908

CORRECTIVE ACTIONS:

1 ☒ CA# 153883

Corrective Action: Comply with Rule 1004.e

Date: 08/02/2021

Response: CA COMPLETED

Date of Completion: 07/26/2021

Operator
Comment: cut and sprayed weeds

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2  CA# 153884

Corrective Action: Comply with Rule 1002.f.(2).C; ensure control measures are adequate for the sites conditions and are installed in accordance with good engineering practices to minimize erosion from unpaved areas, including road surfaces and and cut/fill slopes, and allow for sediment laden-free stormwater discharge. Ensure control measures are maintained in proper functioning condition. Ongoing stormwater monitoring/management required until site receives a passing final inspection

Date: 08/02/2021

Response: CA COMPLETED

Date of Completion: 07/26/2021

Operator
Comment: fixed BMP's on road for stormwater discharge

COGCC Decision: **Not Approved**

COGCC
Representative: Inspection #696202944 documented gully erosion on the north end of the Location (fill slopes).
Operator has not addressed erosion on Location within the FIRR.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Karen Maneotis

Signed:

Title: Production Tech

Date: 7/26/2021 11:09:26 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402759491	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files