

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/05/2021

Submitted Date:

08/05/2021

Document Number:

693505381

FIELD INSPECTION FORM

 Loc ID 319977 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1675 BROADWAY, STE 2800
 City: DENVER State: CO Zip: 80202
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|----------------|---------------------------|----------------------------------|
| Watzman, Ross | (303) 825-4822 | rwatzman@kpk.com | all inspections. |
| , | 303-825-4822 | cogcc@kpk.com | All Inspections |
| Ferrin, Jeremy | | jeremy.ferrin@state.co.us | |
| Gomez, Jason | | jason.gomez@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 202080 | WELL | PR | 03/01/2020 | OW | 001-07485 | BREDEHOFT 1 | PR |

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|------------|
| Type | Ignitor/Combustor | | |
| Comment: | At time of inspection location appears to be flaring gas natural gas that is produced from well, see pic 1 | | |
| Corrective Action: | Contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details. | Date: | 08/24/2020 |

Inspected FacilitiesFacility ID: 202080 Type: WELL API Number: 001-07485 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 10/06/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|---|---------|------------|
| <p>COGCC Inspection Report Summary On Thursday August 5, 2021 at approximately 11:15, I, Inspector Randy Silver, conducted an follow up on-site inspection per doc# 699501648. Location: Bredehoft Operator: KP Kauffman API#:00107485 County: Adams While there, I observed well site and production facility. During this inspection the following possible compliance issues were observed: Flaring: Rule 912 b Corrective action date of 8-24-20 At time of inspection location appears to be flaring gas natural gas that is produced from Well from production tank to ECD. No visible sales gas line on Production facility. Weather conditions: Dry A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> | silverr | 08/05/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 693505382 | loc pic | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5499083 |