

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402432766

Date Received:
06/26/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Victoria Dizghinjili

303-825-4822

vdizghinjili@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693502619

Inspection Date: 04/02/2020

FIR Submit Date: 04/02/2020

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 320470

Location Name: MCELWAIN-61S67W Number: 17NWSW County: ADAMS

Qtrqr: NWS Sec: 17 Twp: 1S Range: 67W Meridian: 6
W

Latitude: 39.964444 Longitude: -104.920278

FACILITY - API Number: 05-001- -00 Facility ID: 256802

Facility Name: MCELWAIN Number: 13-17

Qtrqr: NWS Sec: 17 Twp: 1S Range: 67W Meridian: 6
W

Latitude: 39.964444 Longitude: -104.920278

CORRECTIVE ACTIONS:

1 ☒ CA# 137694

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).

Date: 04/23/2020

Response: CA COMPLETED

Date of Completion: 06/15/2020

Operator
Comment:

All equipment including a tank has been removed from location. Please see attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 137695

Corrective Action: Install sign to comply with Rule 210.d.

Date: 04/23/2020

Response: CA COMPLETED

Date of Completion: 06/15/2020

Operator
Comment: Tank with inaccurate sign has been removed from location. Please see attached picture of location.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 137696

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 04/23/2020

Response: CA COMPLETED

Date of Completion: 06/15/2020

Operator
Comment: CA is completed. Please see attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 ☒ CA# 137697

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 04/23/2020

Response: CA COMPLETED

Date of Completion: 06/15/2020

Operator
Comment: CA is completed. Please see attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

5 ☒ CA# 137698

Corrective Action: Comply with Rule 603.f .

Date: 04/03/2020

Response: CA COMPLETED

Date of Completion: 06/15/2020

Operator
Comment: Risers have been removed from location. Please see attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed: _____

Title: Engineering TechDate: 6/26/2020 2:47:56 PM**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402432766	FIR RESOLUTION SUBMITTED
402432800	Removed equipment PIC1
402432801	Removed equipment PIC2

Total Attach: 3 Files