

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402769171

Date Received:
08/11/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

| | | |
|-----------------------------|---------------------|-----------------------------|
| Contact Name | Phone | Email |
| <u>Victoria Dizghinjili</u> | <u>303-825-4822</u> | <u>vdizghinjili@kpk.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 699304017
Inspection Date: 06/18/2021 FIR Submit Date: 06/18/2021 FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 318598

Location Name: ELKHORN COMPANY B-62N67W Number: 21NWNW County: WELD
Qtrqtr: NWN Sec: 21 Twp: 2N Range: 67W Meridian: 6
W
Latitude: 40.129410 Longitude: -104.903020

FACILITY - API Number: 05-123-00 Facility ID: 241699

Facility Name: ELKHORN COMPANY B Number: 6
Qtrqtr: NWN Sec: 21 Twp: 2N Range: 67W Meridian: 6
W
Latitude: 40.129410 Longitude: -104.903020

CORRECTIVE ACTIONS:

1 CA# 152004

Corrective Action: Comply with Rule 430, Provide calibration records or calibrate meter as required within 30 days. Proof of calibration may be provided on a Field Inspection Resolution Report (FIRR). Date: 07/18/2021

Response: CA COMPLETED Date of Completion: 07/26/2021

Meter is a property of DCP. KPK will submit a request to DCP to have a meter calibrated to comply with rule 430.d.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 152005

Corrective Action: Comply with Rule 1002..(2).D, Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 06/24/2021

Response: CA COMPLETED

Date of Completion: 07/26/2021

Operator
Comment:

Stained soil have been removed at wellhead and at various locations through out TB location. Please see attached picture.

COGCC Decision:

COGCC
Representative:

3 CA# 152006

Corrective Action: Comply with Rule 606

Date: 07/02/2021

Response: CA COMPLETED

Date of Completion: 07/26/2021

Operator
Comment:

Weeds have been removed at well location and lease road. Please see attached pictures.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed: _____

Title: Engineering Tech

Date: 8/11/2021 3:53:58 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| Document Number | Description |
|------------------------|---------------------------------|
| 402769223 | Stained soil removed PIC1 |
| 402769225 | Weeds removed PIC2 |
| 402777277 | Stained soil removed at TB PIC3 |
| 402777280 | Stained soil removed at TB PIC4 |

Total Attach: 4 Files