

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2021

Submitted Date:

08/10/2021

Document Number:

700703104

FIELD INSPECTION FORM

Loc ID 334860	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 9 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 10531 Name of Operator: GRIZZLY OPERATING LLC Address: 5847 SAN FELIPE #3000 City: HOUSTON State: TX Zip: 77057				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211271	WELL	PR	10/01/2013	OW	045-07030	GIBSON GULCH UNIT 11-32	PR
276114	WELL	PR	02/25/2016	GW	045-10425	GGU MILLER 13A-32-691	PR
276116	WELL	PR	12/29/2005	GW	045-10423	GGU MILLER 13C-32-691	PR
276117	WELL	PR	12/28/2005	GW	045-10422	GGU MILLER 23A-32-691	PR
276120	WELL	PR	01/16/2006	GW	045-10420	GGU MILLER 23D-32-691	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 8/10/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP GGU 11-32, at Location # 334860 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area and the 411 water protection area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.

C/A (stabilization of location) from previous inspection document # 700702692 have been completed. Pad was dragged.

During this inspection the following compliance issues were observed:

1. A couple separators are lacking labels for heated baths (Glycol)

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	A couple separators are lacking labels for heated baths (Glycol		
Corrective Action:	Provide proper labeling	Date:	09/10/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Type	TANK BATTERY			
Comment:				
Corrective Action:			Date:	

Equipment:			corrective date
Type: Bradenhead	# 5		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	3	200 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 211271 Type: WELL API Number: 045-07030 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 276114 Type: WELL API Number: 045-10425 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 276116 Type: WELL API Number: 045-10423 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 276117 Type: WELL API Number: 045-10422 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 276120 Type: WELL API Number: 045-10420 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						
		Culverts				
		Check Dams				
Ditches						

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area and the 411 water protection area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402775948	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5502792
700703110	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5502781