

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402785766

Date Received:
08/19/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

970-285-9377

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700703158

Inspection Date: 08/17/2021

FIR Submit Date: 08/18/2021

FIR Status: _____

Inspected Operator Information:

Company Name: GRIZZLY OPERATING LLC

Company Number: 10531

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 415310

Location Name: GGU FED (MDP PAD #9) Number: 22B-28-691 County: _____

Qtrqr: SENW Sec: 28 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.500768 Longitude: -107.561800

FACILITY - API Number: 05-045- -00 Facility ID: 415310

Facility Name: GGU FED (MDP PAD #9) Number: 22B-28-691

Qtrqr: SENW Sec: 28 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.500768 Longitude: -107.561800

CORRECTIVE ACTIONS:

1 CA# 154974

Corrective Action: Provide proper labeling

Date: 09/20/2021

Response: CA COMPLETED

Date of Completion: 08/19/2021

Operator
Comment:

COGCC Rules do not require that production separators be labeled. See attached response.

COGCC Decision: _____

COGCC
Representative:

2 CA# 154975

Corrective Action: Remove unused equipment

Date: 10/01/2021

Response: CA COMPLETED

Date of Completion: 08/19/2021

Operator Comment: The Colorado Air Pollution Control Division (APCD) currently requires the use of air pollution control equipment (e.g., enclosed combustor) on all produced water and condensate storage tanks with ≥ 2 tpy uncontrolled VOC emissions. TEP utilizes enclosed combustors (ECD) to comply with this regulation. When uncontrolled emissions fall below the 2 tpy threshold, TEP will often disconnect the ECD from the tank battery. However, due to the potential of a future increase in the facility emissions or a future reduction of the control threshold, TEP will often elect to leave the ECD in place. An ECD in this status is not "unused equipment", it is temporarily out of service.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed:

Title: TEP ENV

Date: 8/19/2021 12:29:24 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402785976	Correspondence
-----------	----------------

Total Attach: 1 Files