

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402785402

Date Received:

08/19/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

TEP

Phone

970-285-9377

Email

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700703156

Inspection Date: 08/17/2021

FIR Submit Date: 08/18/2021

FIR Status: _____

Inspected Operator Information:

Company Name: GRIZZLY OPERATING LLC

Company Number: 10531

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 335202

Location Name: GIBSON GULCH UNIT-66S91W Number: 29SENW County: _____

Qtrqtr: SENW Sec: 29 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.501044 Longitude: -107.580504

FACILITY - API Number: 05-045-00 Facility ID: 335202

Facility Name: GIBSON GULCH UNIT-66S91W Number: 29SENW

Qtrqtr: SENW Sec: 29 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.501044 Longitude: -107.580504

CORRECTIVE ACTIONS:

1 ☒ CA# 154972

Corrective Action: Remove unused equipment

Date: 10/01/2021

Response: CA COMPLETED

Date of Completion: 08/19/2021

Operator Comment: The Colorado Air Pollution Control Division (APCD) currently requires the use of air pollution control equipment (e.g., enclosed combustor) on all produced water and condensate storage tanks with ≥ 2 tpy uncontrolled VOC emissions. TEP utilizes enclosed combustors (ECD) to comply with this regulation. When uncontrolled emissions fall below the 2 tpy threshold TEP will often disconnect the ECD from the tank battery. However, due to the potential of a future increase in the facility emissions or a future reductions of the control threshold, TEP will often elect to leave the ECD in place. An ECD in this status is not "Unused Equipment", it is "temporarily out

of service." The ECD will remain in place and used as needed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective Action has been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP ENV

Date: 8/19/2021 8:23:02 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402785402	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files