

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402778666

Date Received:

08/12/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Victoria Dizghinjili

Phone

303-825-4822

Email

vdizghinjili@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697601473

Inspection Date: 08/05/2021

FIR Submit Date: 08/06/2021

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 476325

Location Name: Premium Turkey Farms Number: _____ County: _____

Qtrqr: SWNE Sec: 22 Twp: 2N Range: 67W Meridian: 6

Latitude: 40.126672 Longitude: -104.873207

FACILITY - API Number: 05-123- -00 Facility ID: 478861

Facility Name: Premium Turkey Farm PW Vault Number: _____

Qtrqr: SWNE Sec: 22 Twp: 2N Range: 67W Meridian: 6

Latitude: 40.126672 Longitude: -104.873207

CORRECTIVE ACTIONS:

1 ☒ CA# 154608

Corrective Action: Operators will properly store, handle and manage all E&P waste to prevent contamination of stormwater, surface water, groundwater and soil. Manage stormwater around spill site in manner that prevents impacts to those matrices.

Date: 08/07/2021

Response: CA COMPLETED

Date of Completion: 08/07/2021

Operator Comment: Stained soil at exavation has benn removed. Please see attached pictures.

COGCC Decision: Approved pending re-inspection

COGCC Representative: photo documentation provided

2 ☒ CA# 154609

Corrective Action: repair and maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended. The site was not attended at the time of the inspection but has been attended by operator staff in other inspection. Excavation is on an active livestock operation.

Date: 08/07/2021

Response: CA COMPLETED

Date of Completion: 08/07/2021

Operator Comment: Fallen fencing around excavation has been re-installed. Please see attached pictures. Weeds have been removed and the area was sprayed after.

COGCC Decision: Approved pending re-inspection

COGCC Representative: photo documentation provided

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed: _____

Title: Engineering Tech

Date: 8/12/2021 2:02:28 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402778666	FIR RESOLUTION SUBMITTED
402778727	CA completed PIC1
402778732	CA completed PIC2
402778738	CA completed PIC3

Total Attach: 4 Files