

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		Date: _____
Corrective Action:			

Good Housekeeping:			
Type	WEEDS		
Comment:	Few weeds grown around well need to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	09/10/2021
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment around well needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	09/10/2021

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	#		
Comment:	Appears to be leaking from union fix or replaced. See attached photo.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 09/10/2021

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 249614 Type: WELL API Number: 123-17417 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/09/2020 Annual Brhd Completed? No
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: No updated annual bradenhead test on file. Submit reports.
 Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 8/23/21 at approximately 1026hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Ocoma 31-26 of K.P. Kauffman, at Location ID # 332668 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Few weeds grown around the well needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 9/10/21 Unused equipment around the well needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 9/10/21 Appears to be leaking from union fix or replaced. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 9/10/21 See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	08/23/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402789294	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5512934
699104315	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5512927