

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/23/2021

Submitted Date:

08/23/2021

Document Number:

699104322**FIELD INSPECTION FORM**Loc ID 327605 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Kraich, Adam		adam.kraich@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247120	WELL	PR	03/01/2019	GW	123-14917	OCOMA 31-19	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well is missing well sign and needs installed. See attached photos		
Corrective Action:	Install sign to comply with Rule 605.d	Date:	09/10/2021

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil under master valve needs to be removed. See attached photo.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	09/10/2021

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	#		
Comment:	Appears to be leaking from master valve fix or replaced. See attached photo.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 09/10/2021

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 247120 Type: WELL API Number: 123-14917 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 07/09/2020Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0Comment: No updated annual bradenhead test on file. Submit reports.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 8/23/21 at approximately 1037hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Ocoma 31-19 of K.P. Kauffman, at Location ID # 327605 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Well is missing well sign and needs installed. Install sign to comply with Rule 605.d. With a corrective action date of 9/10/21</p> <p>Stained soil under master valve needs to be removed. "Properly dispose of oily waste in accordance with 905.e."With a corrective action date of 9/10/21</p> <p>Appears to be leaking from master valve fix or replaced. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 9/10/21</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	08/23/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402789295	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5512935">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5512935</a>
699104323	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5512931">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5512931</a>