

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402723819

Date Received:
06/21/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Jones, Tammy</u>		<u>tajones@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903191
Inspection Date: 05/17/2021 FIR Submit Date: 05/18/2021 FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326556

Location Name: HUBER-N35N8W Number: 24NENE County: LA PLATA
Qtrqr: NENE Sec: 24 Twp: 35N Range: 8W Meridian: N
Latitude: 37.291640 Longitude: -107.689930

FACILITY - API Number: 05-067- -00 Facility ID: 257076

Facility Name: HUBER Number: 3-24
Qtrqr: NENE Sec: 24 Twp: 35N Range: 8W Meridian: N
Latitude: 37.291640 Longitude: -107.689930

CORRECTIVE ACTIONS:

1 ☒ CA# 151108

Corrective Action: -Stormwater BMPs need to be installed to stabilize erosion along the access road. BMPs need to be selected, sized, installed, and maintained according to good engineering practices such as those described by CDOT in their erosion control manuals. Corrective action is back-dated to 7/5/2019 as original response to corrective action was not adequate.

Date: 07/05/2019

Response: CA COMPLETED Date of Completion: 06/16/2021

Attached are picture of the completed work. Crew cleaned out existing rock check dams, rebuilt them and added additional one to prevent soil erosion on road way. Work was completed 6-16-21.

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 6/21/2021 6:44:30 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402723819	FIR RESOLUTION SUBMITTED
402723820	Huber 3-24 Resolved Photos

Total Attach: 2 Files