

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/27/2021

Submitted Date:

08/30/2021

Document Number:

693700855

FIELD INSPECTION FORM

Loc ID 317496 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 42950

Name of Operator: INDUSTRIAL GAS SERVICES INC

Address: 4891 INDEPENDENCE ST STE 200

City: WHEATRIDGE State: CO Zip: 80033

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Petrie, Erica		erica.petrie@state.co.us	
		igsinc@att.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238354	WELL	SI	05/01/2016	GW	123-05198	BEHRING 1	EI

General Comment:

COGCC Environmental Staff Inspection focused on Remediation Project 7910.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds have overgrown berms around tanks.		
Corrective Action:	Comply with Rule 606 to control weeds		Date: 09/13/2021

Overall Good: ☐

Spills:				
Type	Area	Volume		
Crude Oil	WELLHEAD	<= 1 bbl		
Comment:	Oily waste/oil impacted soil is present around wellhead from historical spill(s)			
Corrective Action:	Remove oil impacted soil and dispose concurrent with oily soil from pit closure. Provide soil sample from wellhead cleanup, analyzed for total petroleum hydrocarbons (TPH C6-C36) and include documentation with Form 27 Supplemental documenting removal of oily waste for Remediation Project 7910.			Date: 10/31/2021

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:				corrective date
Type: Flow Line	#			
Comment:	Flowlines from Heater Treater to pit must be abandoned in accordance with Rule 1103. Contact Engineering Integrity Supervisor Mark Schlagenhauf, mark.schlagenhauf@state.co.us, for questions/guidance on flowline abandonment.			
Corrective Action:	Properly abandon flowlines to former pit. Comply w/ Rule 1103. Original Corrective Action date: 03/20/2017.			Date: 03/20/2017

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PLASTIC AST		40.440350,-104.170070	
Comment:						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate
Comment:	Berms have eroded,			

Corrective Action:	Restore secondary containment berms around produced water tank per Rule 603.e. Corrective Action date concurrent with site work to complete Remediation 7910	Date:	10/31/2021
--------------------	---	-------	------------

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spill/Remediation:**

Comment: [Met Operator onsite to discuss final sampling of land treatment area and commence hauling impacted material for offsite disposal of oily waste as outlined in Form 27 Supplemental Document #402763706.](#)

Corrective Action: [Comply with conditions of approval and deadlines listed on Form 27 Supplemental Document #402763706.](#)

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402796870	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5519163