

TEP
RGU 23-35-198
Location # 316596



location



location



TEP
RGU 23-35-198
Location # 316596



Location/ Glycol storage vessels contains no labeling to specify capacity or chemical hazard information.



lack of bull plug/cap



TEP
RGU 23-35-198
Location # 316596



Lack of stabilization/compaction



Lack of stabilization/compaction

TEP
RGU 23-35-198
Location # 316596



Sep 7, 2021 at 2:47:45 PM
+39.919453, -108.363373 ±4.84r
COGCC

Lack of stabilization/compaction



Sep 7, 2021 at 2:47:21 PM
+39.919359, -108.363415 ±4.83r
COGCC

Lack of stabilization/compaction