

FORM
6Rev
11/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

402657990

Date Received:

08/02/2021

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 69175

Contact Name: Valerie Danson

Name of Operator: PDC ENERGY INC

Phone: (970) 506-9272

Address: 1775 SHERMAN STREET - STE 3000

Fax:

City: DENVER State: CO Zip: 80203

Email: valerie.danson@pdce.com

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report: ☐ Notice of Intent to Abandon ☒ Subsequent Report of Abandonment

API Number 05-123-20209-00

Well Name: BRYCE

Well Number: 1

Location: QtrQtr: SWSE Section: 13 Township: 4N Range: 67W Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WATTENBERG

Field Number: 90750

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.306530

Longitude: -104.836810

GPS Data: GPS Quality Value: 3.0 Type of GPS Quality Value: Date of Measurement: 07/15/2010

Reason for Abandonment: ☐ Dry ☐ Production Sub-economic ☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes ☐ No Estimated Depth:Fish in Hole: ☐ Yes ☐ No If yes, explain details belowWellbore has Uncemented Casing leaks: ☐ Yes ☐ No If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7318	7334	02/19/2021	B PLUG CEMENT TOP	7268

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8		24	0	415	290	415	0	VISU
1ST	7+7/8	4+1/2		11.6	0	7434	700	7434	0	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7268 with 2 sacks cmt on top. CIBP #2: Depth 6943 with 2 sacks cmt on top.
CIBP #3: Depth 4700 with 2 sacks cmt on top. CIBP #4: Depth 2500 with 2 sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 125 sacks half in. half out surface casing from 1460 ft. to 0 ft. Plug Tagged: ☒

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Surface Plug Setting Date: 02/22/2021 Cut and Cap Date: 03/02/2021 Number of Days from Setting Surface Plug to Capping or Sealing the Well: 8

*Wireline Contractor: Rocky Mtn Wireline Services

*Cementing Contractor: DUCO Inc. Cementing Services

Type of Cement and Additives Used: Class G 15.8 PPG Cement

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

Bryce 1 (05-123-20209)/Plugging Procedure

Producing Formation: Codell: 7318'-7334'

Upper Pierre Aquifer: 440'-1360'

TD: 7438' PBTD: 7420' (9/28/15)

Surface Casing: 8 5/8" 24# @ 415' w/ 290 sxs cmt

Production Casing: 4 1/2" 11.6# @ 7434' w/ 700 sxs cmt (TOC @ Surface - CBL)

Procedure:

1. MIRU pulling unit. Pull 2 3/8" tubing.
2. RU wireline company.
3. TIH with CIBP. Set BP at 7268'. Top with 2 sxs 15.8#/gal CI G cement. (Top of Codell perms @ 7318')
4. TIH with CIBP. Set BP at 6943'. Top with 2 sxs 15.8#/gal CI G cement. (Top of Niobrara @ 6993')
5. TIH with CIBP. Set BP at 4700'. Top with 2 sxs 15.8#/gal CI G cement. (Top of Shannon @ 4750')
6. TIH with CIBP. Set BP at 2500'. Top with 2 sxs 15.8#/gal CI G cement.
7. Ran a Strip Log from 1000' to Surface (log not kept).
8. TIH with tubing to 1460'. RU cementing company. Mix and pump 125 sxs 15.8#/gal CI G cement down tubing. Cement circulate to surface.
9. Well casing cut and capped per COGCC guidelines at a depth as not to interfere with soil cultivation.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Valerie Danson

Title: Reg Tech Date: 8/2/2021 Email: valerie.danson@pdce.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved, Eric

COGCC Approved:

Date: 9/21/2021

CONDITIONS OF APPROVAL, IF ANY:

Condition of Approval

COA Type

Description

0 COA

Attachment List

Att Doc Num

Name

402657990	FORM 6 SUBSEQUENT SUBMITTED
402657994	CEMENT JOB SUMMARY
402657995	OTHER
402657997	OPERATIONS SUMMARY
402658001	WELLBORE DIAGRAM

Total Attach: 5 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)