

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/16/2021

Submitted Date:

09/16/2021

Document Number:

699503178

FIELD INSPECTION FORM
 Loc ID 320111 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10711

Name of Operator: PAINTED PEGASUS PETROLEUM LLC

Address: 16820 BARKER SPRINGS RD #521

City: HOUSTON State: TX Zip: 77084

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
		jm@p3petro.com	
Leonard, Mike		mike.leonard@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202657	WELL	PR	01/01/2019	GW	001-08062	HORTH 32-15 2	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment: [stained soil near wellhead from recent workover](#)Corrective Action: [Comply with COGCC housekeeping rules.](#)Date: 10/16/2021Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment: [Plumbed to surface](#)

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: [Plungerlift automation](#)

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 202657 Type: WELL API Number: 001-08062 Status: PR Insp. Status: PR

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: All tubing has been taken out of well except one joint to install wraparound wellhead.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/29/2020 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Bradenhead test was administered on location during time of inspection

Start 1310
Casing 8 PSI Bradenhead 0
5 mins
Casing 8 PSI Bradenhead no flow
10 ins
Casing 8 PSI Bradenhead no flow
15 minutes
Casing 9 PSI Bradenhead no flow
20 minutes
Casing 9 PSI Bradenhead no flow
25 minutes
Casing 9 PSI Bradenhead no flow
30 minutes
Casing 9 PSI Bradenhead no flow

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 9/16/21 at approximately 1330 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Horth 32-15 2 Company Name- P3 API- 05-001-08062 In Adams County Colorado. While there, I observed TA well During this inspection the following possible compliance issues were observed: Stained soil by wellhead see pic 1 Comply with COGCC housekeeping rules. 10/16/21 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. Previous inspection corrective actions may still be valid. This is a summary of inspection report.</p>	medinaj	09/16/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402814748	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5533936
699503179	Inspection Pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5533931