

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402822698

Date Received:  
09/26/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 17180  
Name of Operator: CITATION OIL & GAS CORP  
Address: 14077 CUTTEN RD  
City: HOUSTON State: TX Zip: 77069

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Robert Redweik</u>	<u>281-891-1550</u>	<u>BRedweik@cogc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 700600276  
Inspection Date: 07/13/2021 FIR Submit Date: 07/20/2021 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CITATION OIL & GAS CORP Company Number: 17180  
Address: 14077 CUTTEN RD  
City: HOUSTON State: TX Zip: 77069

LOCATION - Location ID: \_\_\_\_\_

Location Name: \_\_\_\_\_ Number: \_\_\_\_\_ County: \_\_\_\_\_  
Qtrqr: SESE Sec: 25 Twp: 14S Range: 42W Meridian: 6  
Latitude: 38.799195 Longitude: -102.053450

FACILITY - API Number: 05-017-00 Facility ID: 480289

Facility Name: Arapahoe Unit Sec. 25S Tank Battery Number: \_\_\_\_\_  
Qtrqr: SESE Sec: 25 Twp: 14S Range: 42W Meridian: 6  
Latitude: 38.799195 Longitude: -102.053450

CORRECTIVE ACTIONS:

1  CA# 153927

Corrective Action: Inspect, maintain and repair tanks to comply with rule 609.b. Date: 09/20/2021

Response: CA COMPLETED Date of Completion: 07/16/2021

Operator Comment: On July 16, 2021, the fluid was transferred from Tank #17, the equalizer line was disconnected, and the Tank was locked and tagged out of service. Unfortunately, due to the ongoing pandemic, Citation has been unable to locate a crew to remove and replace the tank. Given the work crew shortage to perform this work, it is difficult to estimate when this existing tank may be removed and replaced. Until, that time, the tank will remain logged and tagged out of service.

COGCC Decision: Approved pending re-inspection

COGCC Representative: FIRR approved. Tank has been removed from service and is awaiting replacement.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: See Corrective Action reponse regarding the status of tank repair.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Robert Redweik

Signed: \_\_\_\_\_

Title: Dicector EHS/Regulatory

Date: 9/26/2021 9:09:09 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

402822698	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files