

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402837521

Date Received:
10/11/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10728

Name of Operator: GULF EXPLORATION LLC

Address: 9701 N BROADWAY EXTENSION

City: OKLAHOMA CITY State: OK Zip: 73114

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Parks Barroso

parks.barroso@coag.gov

Scott Schultz

scott.schultz@coag.gov

Sean Strickland

sstrickland@gulfexploration.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692402693

Inspection Date: 11/19/2020

FIR Submit Date: 12/02/2020

FIR Status: _____

Inspected Operator Information:

Company Name: GULF EXPLORATION LLC

Company Number: 10728

Address: 9701 N BROADWAY EXTENSION

City: OKLAHOMA CITY State: OK Zip: 73114

LOCATION - Location ID: 466705

Location Name: Eagle Hill Number: 1-32 Pad County: _____

Qtrqr: NWNE Sec: 32 Twp: 10N Range: 78W Meridian: 6

Latitude: 40.799820 Longitude: -106.170270

FACILITY - API Number: 05-057-00 Facility ID: 466705

Facility Name: Eagle Hill Number: 1-32 Pad

Qtrqr: NWNE Sec: 32 Twp: 10N Range: 78W Meridian: 6

Latitude: 40.799820 Longitude: -106.170270

CORRECTIVE ACTIONS:

1 CA# 144801

Corrective Action: Perform Final Reclamation per COGCC 1004 Rules. Due to enforcement actions CA Date is not given.

Date: _____

Response: CA COMPLETED

Date of Completion: 10/11/2021

Operator Comment: Seed bed preparation and drill seeding were completed on the road and pad areas followed by straw mulching. The blanket work and seeding from last fall was effective and had good growth in the swale so we left it as is so as not to set us back another year on grass establishment.

COGCC Decision: _____

COGCC
Representative:

2 CA# 144802

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 08/19/2019

Response: CA COMPLETED

Date of Completion: 10/11/2021

Operator
Comment:

Compost and Straw Erosion Logs were installed after seeding/mulching to stop any potential erosion. Soil prep, seeding, and straw crimping were completed on the contour to also help with erosion. Contour crimping will help with erosion in the draw.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sean Strickland

Signed: _____

Title: Operations Manager

Date: 10/11/2021 1:38:23 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402837551	Corrective Actions Report
-----------	---------------------------

Total Attach: 1 Files