

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Signs and Markers of permanent designations.		
Corrective Action:	605.d. Signs and Markers of permanent designations. Install sign to comply with Rule 605.h. 30 days if missing 24 hour operator contact number and/or local emergency contact. Corrective Action Date 1/10/2022. See attached photo #1	Date:	01/10/2022

Emergency Contact Number:		
Comment:	Adequate	
Corrective Action:		Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds throughout location		
Corrective Action:	Weeds throughout location and debris from pump jack house. Location is within a designated setback location, remove trash, debris and weeds per Rule 606. Corrective Action Date 11/19/2021. See attached photo #1 - 3 & 6.	Date:	11/19/2021
Type	DEBRIS		
Comment:	debris from pump jack house		
Corrective Action:	Weeds throughout location and debris from pump jack house. Location is within a designated setback location, remove trash, debris and weeds per Rule 606. Corrective Action Date 11/19/2021. See attached photo #1 - 3 & 6.	Date:	11/19/2021

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			

Corrective Action:		Date:	
Type: Pump Jack	#		
Comment:	Stained soil around well head		
Corrective Action:	Stained soil around well head. Control and contain spills/releases and clean up stained soil per Rule 912.aContact COGCC EPS staff. Immediately to stop and clean up 24 hours to remove free fluids. . Corrective Action Date 12/6/2021 to remove stained soil. See attached photo # 5		Date: 12/06/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		39.907247,-104.557341
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
001-09316

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 203756 Type: WELL API Number: 001-09316 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Appears to be plumbed to the surface

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday October 14, 2021 at approximately 14:00pm. I, Inspector Chane Finkenbinder, Conducted an on-site inspection at Hosmer 4-6, Renegade Oil & Gas Company, at API # 001-09316 in Adams County Colorado. While there, I observed a Shut in well. During this inspection the following possible compliance issues were observed: Weeds throughout location and debris from pump jack house. Location is within a designated setback location, remove trash, debris and weeds per Rule 606. Corrective Action Date 11/19/2021. See attached photo #1 - 3 & 6. Stained soil around well head. Control and contain spills/releases and clean up stained soil per Rule 912.a Contact COGCC EPS staff. Immediately to stop and clean up 24 hours to remove free fluids. . Corrective Action Date 12/6/2021 to remove stained soil. See attached photo # 5 605.d. Signs and Markers of permanent designations. Install sign to comply with Rule 605.h. 30 days if missing 24 hour operator contact number and/or local emergency contact. Corrective Action Date 1/10/2022. See attached photo #1</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	11/01/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402859812	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5569959
700900829	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5569951