

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/20/2021

Submitted Date:

11/01/2021

Document Number:

700900837

FIELD INSPECTION FORM

Loc ID 320110 Inspector Name: Finkenbinder, Chane On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10711
Name of Operator: PAINTED PEGASUS PETROLEUM LLC
Address: 16820 BARKER SPRINGS RD #521
City: HOUSTON State: TX Zip: 77084

Findings:

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Mustacchia, Joey		jmustacchia@p3petro.com	
Hubbard, Keith		khubbard@p3petro.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202656	WELL	SI	09/01/2019	GW	001-08061	ATWATER 4 24-1	SI

General Comment:

(This area is currently blank for general comments.)

Location

Lease Road:			
Type	Access		
comment:	Access roads not maintained		
Corrective Action:	Access roads not maintained. Location is within a designated setback location, maintain and repair access roads / provide key to access location per Rule 204. Corrective Action Date 12/10/2021. See attached photo #4.	Date:	12/10/2021

Overall Good:

Emergency Contact Number:		
Comment:	Adequate	
Corrective Action:		Date: _____

Good Housekeeping:		
Type	WEEDS	
Comment:	Weeds throughout location	
Corrective Action:	Weeds throughout location. Location is within a designated setback location, remove trash, debris and weeds per Rule 606. Corrective Action Date 11/19/2021. See attached photo #1 through 4.	Date: 11/19/2021

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		39.812019,-104.501002
Comment:					
Corrective Action:					Date:

Paint				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:
Wells Served By Facilities Above				
API Number		AirsID		
001-08061		API Number	AirsID	
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 202656 Type: WELL API Number: 001-08061 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Appears to be plumbed to surface

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday October 20, 2021 at approximately 9:15am. I, Inspector Chane Finkenbinder, Conducted an on-site inspection at Atwater 4-24-1, Painted Pegasus Petroleum LLC, at API # 001-08061 in Adams County Colorado. While there, I observed a shut in well. During this inspection the following possible compliance issues were observed: Weeds throughout location. Location is within a designated setback location, remove trash, debris and weeds per Rule 606. Corrective Action Date 11/19/2021. See attached photo #1 through 4. Access roads not maintained. Location is within a designated setback location, maintain and repair access roads / provide key to access location per Rule 204. Corrective Action Date 12/10/2021. See attached photo #4. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	11/01/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402859816	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5569963
700900838	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5569955