

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/09/2021

Submitted Date:

11/09/2021

Document Number:

701102191

**FIELD INSPECTION FORM**Loc ID 314355 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10556

Name of Operator: PLUG NICKEL OIL COMPANY INC

Address: PO BOX 1937

City: VERNAL State: UT Zip: 84078

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Hogue, Jimmy	435-828-7666	hogue@stratanet.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228535	WELL	PR	06/01/2021	OW	103-05424	HUSKY 20	PR

**General Comment:**

COGCC Routine Inspection Report Summary

Location is in a High Priority Habitat Area.

During this inspection the following compliance issues were observed:

- No api # on well sign.
- No api# on tank battery sign.
- Dead weed debris on location.
- Unstable cutslope behind tank battery. Sediment built up to tank berm.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	No api # on well sign.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	02/15/2022
Type	BATTERY		
Comment:	No api # on well sign.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	02/15/2022
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Dead weed debris on location.		
Corrective Action:	Comply with Rule 606	Date:	11/27/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 0		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	200 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	228535	Type:	WELL	API Number:	103-05424	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well Pump jack idle at time of inspection								
Corrective Action:								Date:	

--	--	--	--	--	--	--	--	--	--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
Berms						

Comment: Unstable cutslope behind tank battery. Sediment built up to tank berm.Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)CDate: 11/27/2021**Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402868355	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5578012">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5578012</a>
701102192	Inspection 701102191 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5578008">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5578008</a>