

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/18/2021

Submitted Date:

11/18/2021

Document Number:

693505895**FIELD INSPECTION FORM**Loc ID 319977 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
,	303-825-4822	cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202080	WELL	PR	03/01/2020	OW	001-07485	BREDEHOFT 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Sign not posted or information inaccurate at well(s)		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	12/18/2021

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Dead weeds on location		
Corrective Action:	Comply with rule 606	Date:	12/18/2021

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		39.987973,-104.940076
Comment:	Crude oil tank has been tagged and paint is peeling on top edge and under catwalk.				
Corrective Action:	Production facility is clearly visible from a public highway, road, or publicly-maintained trail. Facility paint is not uniform, non-contrasting, non-reflective color tones (similar to the Munsell Soil Color Coding System), and with colors matched to but slightly darker than the surrounding landscape. Paint production facilities per Rule 425.				Date: 12/18/2021

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 202080 Type: WELL API Number: 001-07485 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/23/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type:

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Thursday November 18, 2021 at approximately 11:08AM I, Inspector Randy Silver, conducted an on-site inspection.
 Location: Bredehoft #1
 Operator: KP Kauffman
 API#: 001-07485
 County: Adams
 While there, I observed a production facility
 During this inspection the following possible compliance issues were observed:
 Debris: Rule 606 Corrective action date of 12-18-21 see photos
 BTRY sign: Rule 605 d Corrective action date of 12-18-21 See photo
 Visual impact: Rule 425 Corrective action date of 12-18-21
 Weather conditions: Clear and dry
 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

silverr

11/18/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
693505896	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5584185