

TEP
Fed 399-1-2
Location # 316508



location



location

TEP
Fed 399-1-2
Location # 316508



location



Glycol vessel lacking labeling



TEP
Fed 399-1-2
Location # 316508



Staining under threaded ball valve/ possibly slow leak



Unused/stored equipment



TEP
Fed 399-1-2
Location # 316508



Debris



Load line missing cap/bull plug



TEP
Fed 399-1-2
Location # 316508



Access lack of stabilization/compaction



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources