

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/16/2021

Submitted Date:

11/17/2021

Document Number:

697503508

FIELD INSPECTION FORM

Loc ID 331236 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
331236	LOCATION	AC			-	DEEPE 14N-27HZ	RI

General Comment:

This is an interim reclamation inspection in response to a KPK complaint. COGCC Staff believes Kerr McGee (Oxy) to be in violation regarding the use of an access road, not KPK.

Location**Lease Road:**

Type	Main		
comment:	After reviewing relevant files and historic aerial imagery, COGCC Staff believes KPK is utilizing a pre-existing access road prior to the new Kerr McGee (Oxy) Deep locations. Oxy planned and was approved to utilize the pre-existing access road illustrated in Photo #1. However, Oxy built a new access road that was not approved. Refer to the attached inspection photos.		
Corrective Action	L	Date:	
Type	Main		
comment:	Oxy failed to comply with the approved Form 2A's for Location ID 331236 (Doc.# 400489957) and Location ID 435424 (Doc.# 400509105) regarding the approved access road; therefore, also violating Rule 1002.e.(4) to minimize surface disturbance.		
Corrective Action	L	Date:	12/01/2021
<p>Oxy shall come to an agreement with KPK on which access road to utilize. If all parties agree to utilize the new Oxy access road, then Oxy shall reclaim the pre-existing access road illustrated in Photo #1. If all parties agree to utilize the pre-existing access road, then Oxy shall reclaim the new Oxy access road that was not approved.</p> <p>Oxy will be given two weeks to reach an agreement.</p> <p>Oxy shall make every reasonable effort to complete reclamation on whichever access road needs to be reclaimed before the next local growing season.</p>			

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

Inspector Name: Binschus, Chris

Comment:						Date _____
Corrective Action:						
Overall Final Reclamation		Well Release on Active Location <input type="checkbox"/>		Multi-Well Location <input type="checkbox"/>		
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:					At the time of this inspection, no erosion issues were observed.	
Corrective Action:						
					Date: _____	
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402873285	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5583183
697503509	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5583182