

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402882875

Date Received:

11/30/2021

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903817

Inspection Date: 10/29/2021

FIR Submit Date: 11/04/2021

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 326125

Location Name: TUBBS 32-6-9-N32N6W Number: 9SESW County: LA PLATA

Qtrqr: SESW Sec: 9 Twp: 32N Range: 6W Meridian: N

Latitude: 37.027501 Longitude: -107.510165

FACILITY - API Number: 05-067-00 Facility ID: 215912

Facility Name: TUBBS 32-6-9 A Number: 1

Qtrqr: SESW Sec: 9 Twp: 32N Range: 6W Meridian: N

Latitude: 37.027501 Longitude: -107.510165

CORRECTIVE ACTIONS:

1 CA# 157463

Corrective Action: -Remove and properly dispose of debris by 11/20/2021. Manage weeds to prevent debris.

Date: 11/20/2021

Response: CA COMPLETED

Date of Completion: 11/30/2021

Operator Comment: completed. see attached work completed

COGCC Decision: _____

COGCC
Representative:

2 CA# 157464

Corrective Action: Treat and remove saltcedar trees by 11/20/2021.

Date: 11/20/2021

Response: CA COMPLETED

Date of Completion: 11/23/2021

Operator
Comment: treated and removed salt cedar trees see attached pdf work completed

COGCC Decision:

COGCC
Representative:

3 CA# 157465

Corrective Action: -Erosion controls such as crimped in mulch, hydromulch, straw blanket, etc., need to be installed and maintained in the western project area until stabilized with desirable perennial vegetation, by 11/20/2021.

Date: 11/20/2021

Response: CA COMPLETED

Date of Completion: 11/30/2021

Operator
Comment: This corrective action is NOT located on SIMCOE Wellsite pad. It is a LOGOS Operating LLC called Tubbs #001MV, API number is 05-067-05780. (photo attached of sign). Please review location of photo 5 in original FIR as this is not a SIMCOE site and is not within the SIMCOE well pad area.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Please review 3rd corrective action. It is not a SIMCOE location. See attached picture of operator and asset owner. other CA are completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Karin Rhodes

Signed:

Title: admin asst

Date: 11/30/2021 1:44:09 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|---|
| 402882903 | 2 CAs completed |
| 402882910 | Logos Sign for area noted in CA for erosion control |
| 402882911 | original written order - see photo 5 |

Total Attach: 3 Files