

FORM

6

Rev
11/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

402833728

Date Received:

10/06/2021

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120

Contact Name: CANDICE BARBER

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Phone: (307) 233-4513

Address: P O BOX 173779

Fax:

City: DENVER State: CO Zip: 80217-

Email: CANDICE_BARBER@OXY.COM

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report:



Notice of Intent to Abandon



Subsequent Report of Abandonment

API Number 05-123-16360-00

Well Name: HSR-BIG GEORGE

Well Number: 14-35

Location: QtrQtr: SESW

Section: 35

Township: 4N

Range: 66W

Meridian: 6

County: WELD

Federal, Indian or State Lease Number: 61515

Field Name: WATTENBERG

Field Number: 90750

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.263793

Longitude: -104.747938

GPS Data: GPS Quality Value: 1.3

Type of GPS Quality Value: PDOP

Date of Measurement: 09/16/2021

Reason for Abandonment:



Dry



Production Sub-economic



Mechanical Problems

☐ Other

Casing to be pulled:



Yes



No

Estimated Depth:

Fish in Hole:



Yes



No

If yes, explain details below

Wellbore has Uncemented Casing leaks:



Yes



No

If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7302	7315	07/06/2021	B PLUG CEMENT TOP	6940
NIOBRARA	7007	7179	07/06/2021	B PLUG CEMENT TOP	6940
J SAND	7770	7816	09/01/2008	SAND PLUG	7700

Total: 3 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J-55	24	0	446	310	446	0	VISU
1ST	7+7/8	4+1/2	I-70	11.6	0	8067	556	8082	6170	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6940 with 2 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.

CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.

CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 2 sks cmt from 7595 ft. to 7575 ft.

Plug Type: CASING

Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft.

Plug Type: _____

Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft.

Plug Type: _____

Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft.

Plug Type: _____

Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft.

Plug Type: _____

Plug Tagged: ☐

Perforate and squeeze at 4590 ft. with 147 sacks. Leave at least 100 ft. in casing 4105 CICR Depth

Perforate and squeeze at 2490 ft. with 225 sacks. Leave at least 100 ft. in casing 2060 CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 120 sacks half in. half out surface casing from 550 ft. to 340 ft.

Plug Tagged: ☒

Set 19 sacks at surface

Cut four feet below ground level, weld on plate

Above Ground Dry-Hole Marker: ☐ Yes

☒ No

Set _____ sacks in rat hole

Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 550 ft. of 4+1/2 inch casing

Number of Days from Setting Surface Plug to Capping or Sealing the Well: 65

Surface Plug Setting Date: 07/13/2021 Cut and Cap Date: 09/16/2021

*Wireline Contractor: CUTTERS

*Cementing Contractor: SCHLUMBERGER

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes

☐ No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: CANDICE BARBER

Title: REGULATORY ANALYST

Date: 10/6/2021

Email: DJPOSTDRILL@ANADARKO.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jacobson, Eric

Date: 12/3/2021

CONDITIONS OF APPROVAL, IF ANY:

Condition of Approval

COA Type**Description**

0 COA

Attachment List

Att Doc Num**Name**

402833728	FORM 6 SUBSEQUENT SUBMITTED
402833743	OPERATIONS SUMMARY
402833744	OTHER
402833747	CEMENT JOB SUMMARY
402833748	OTHER
402833749	WELLBORE DIAGRAM
402833750	OTHER
402833753	WIRELINE JOB SUMMARY

Total Attach: 8 Files

General Comments

User Group**Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)