

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/24/2021

Submitted Date:

12/01/2021

Document Number:

689806692

FIELD INSPECTION FORMLoc ID 313167 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10677

Name of Operator: WOLVERINE RESOURCES LLC

Address: 109 EAST 17TH STREET #430

City: CHEYENNE State: WY Zip: 82001

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Reeves, Shane		shane@wolverineresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267927	WELL	SI	08/01/2019	GW	081-07131	SCHROEDER 33-32	SI

General Comment:

Routine follow up inspection. Follow up to inspection from 5/20/2021 document number 689805844. No corrective actions appear to have been met. The below summary and corrective action dates remain from that inspection.

Equipment stored on location, amount of equipment stored has increased. Equipment is not stored neatly. Equipment is inside deadman perimeter. Comply with Rule 606 by 3/5/2018.

Flowline risers not LO/TO or marked are considered unused equipment. 2 - 2" steel risers not in use at 40.78107, -107.85588 and 4 - 1" steel risers and 3 - 2" steel risers at 40.78109, -107.85619.

Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Produce well after performing successful mechanical integrity test per Rule 417.b or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention by 7/10/2020.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	303-241-5523	Date:	
Corrective Action:			

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Amount of equipment stored has increased. Equipment is not stored neatly. Equipment is inside deadman perimeter.		
Corrective Action:	Comply with Rule 606.	Date:	03/05/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heater Treater	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 267927 Type: WELL API Number: 081-07131 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417.b or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 07/13/2020

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater BMPs observed. No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402891200	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5599870
689806693	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5599859