

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2021

Submitted Date:

12/16/2021

Document Number:

694500375**FIELD INSPECTION FORM**Loc ID 430051 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10525Name of Operator: SANTA FE NATURAL RESOURCES INCAddress: 4833 FRONT STREET UNIT B 506City: CASTLE ROCK State: CO Zip: 80104**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****General Comment:**

On 12/14/2021 COGCC staff, Kris Neidel inspected the Ridgeview #32-16-1. The weather was 45 degrees and snow covered most of the ground. The snow cover made observation of the soil difficult. The well was PA and all production equipment has been removed. The flare pit had part of the berm removed and the bottom appeared to have been disturbed with an excavator recently. Part of the secondary containment was removed at the Treater and Tank battery. There were multiple piles of soil. There was a pile of what appeared to be cement wash out. There is a Remediation project for Rule 911 for this location. Corrective Actions: The wash out cement pile shall be removed and not incorporated in reclamation. Approved workplan to delineate any remaining impact shall be completed at a time where the ground is observable (not covered in snow). See photos.

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Workover	Piles	Adequate		
Comment	a pile of cement, appears to be wash out from PA.			
Corrective Action	cement can NOT be used in surface reclamation.			Date:

Spill/Remediation:

Comment:	
Corrective Action:	Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500376	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5609639