

FORM  
INSPRev  
X/20

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/05/2021

Submitted Date:

11/30/2021

Document Number:

700900925

### FIELD INSPECTION FORM

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
319645 \_\_\_\_\_ Finkenbinder, Chane \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10711  
Name of Operator: PAINTED PEGASUS PETROLEUM LLC  
Address: 16820 BARKER SPRINGS RD #521  
City: HOUSTON State: TX Zip: 77084

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 5 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hubbard, Keith		khubbard@p3petro.com	
Mustacchia, Joey		jmustacchia@p3petro.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
200669	WELL	SI	01/01/2019	GW	001-06072	JAN 1	SI

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds throughout location		
Corrective Action:	Location is within a designated setback location, remove trash, debris and weeds per Rule 606. Corrective Action Date 12/17/2021. See attached photo # 1 through 3.		Date: 12/17/2021

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	Comment:	Corrective Action:	Date:	corrective date
Horizontal Heated Separator	# 1				
Bird Protectors	# 1				
Gas Meter Run	# 1				
Plunger Lift	# 1				
Deadman # & Marked	# 4				

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.943923,-104.124650
Comment:	Stained soil around tank.				
Corrective Action:	Stained soil around tank. Control and contain spills/releases and clean up per Rule 905.e. Corrective Action Date 12/31/2021 to remove stained soil. See attached photo #4				Date: 12/31/2021

**Paint**

Condition: Adequate

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Wells Served By Facilities Above**

**AirsID**

API Number	API Number	AirsID
001-06072		

**Venting:**

	Yes/No	NO			
Comment:					
Corrective Action:					Date:

**Flaring:**

Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 200669 Type: WELL API Number: 001-06072 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On Friday November 5, 2021 at approximately 12:39pm. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Jan 1, Painted Pegasus Petroleum LLC, at API # 001-06072 in Adams County Colorado.                      While there, I observed a shut in well.                      During this inspection the following possible compliance issues were observed:                      Dead Weeds, trash, debris &amp; unnecessary equipment. Location is within a designated setback location, remove trash, debris and weeds per Rule 606. Corrective Action Date 12/17/2021. See attached photo # 1 through 3.                      Stained soil around tank. Control and contain spills/releases and clean up per Rule 905.e. Corrective Action Date 12/31/2021 to remove stained soil. See attached photo #4</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	finkenbc	11/30/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402897708	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5606142">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5606142</a>
700900926	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5606135">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5606135</a>