

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/21/2021

Submitted Date:

12/29/2021

Document Number:

688311750**FIELD INSPECTION FORM**Loc ID 305047 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Foundation Energy	(866) 767-3600	regulatory@foundationenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277701	WELL	PR	02/08/2006	GW	125-09293	PRATHER 21-12	PR

General Comment:[Reinspection-passed, 2021 gas meter calibration card is present](#)

Inspected FacilitiesFacility ID: 277701 Type: WELL API Number: 125-09293 Status: PR Insp. Status: PR**Producing Well**Comment: [pr 10/1/2021 production is reported to COGCC database.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					

Comment: Continued stuffing box leak at wellhead cause produced water to leave location (under fence at wellhead) and eroded into pasture (see attached photos).

Corrective Action: Install or repair required BMPs per Rule 1002.f(2)C

Date: 01/13/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688311816	Foundation Energy Prather 21-12 REIN	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5619998