

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402926375

Date Received:  
01/13/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1875 LAWRENCE ST STE 1150  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name Phone Email  
Distribution, Evergreen cogcc.evergreen@enrllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 695105088  
Inspection Date: 11/04/2021 FIR Submit Date: 11/04/2021 FIR Status:

Inspected Operator Information:

Company Name: EVERGREEN NATURAL RESOURCES LLC Company Number: 10705  
Address: 1875 LAWRENCE ST STE 1150  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 308795

Location Name: LPGC-632S65W Number: 32SWNE County: LAS ANIMAS  
Qtrqr: SWNE Sec: 32 Twp: 32S Range: 65W Meridian: 6  
Latitude: 37.216620 Longitude: -104.691860

FACILITY - API Number: 05-071- -00 Facility ID: 281855

Facility Name: LPGC Number: 32-32  
Qtrqr: SWNE Sec: 32 Twp: 32S Range: 65W Meridian: 6  
Latitude: 37.216620 Longitude: -104.691860

CORRECTIVE ACTIONS:

1 CA# 157558

Corrective Action: ADJUST SOLAR PANEL OR MOVE WELL SIGN SO SIGN CAN BE EASILY SEEN FROM A DISTANCE PER RULE 605.a. Date: 12/04/2021

Response: CA COMPLETED Date of Completion: 01/11/2022

Operator Comment: Adjusted solar panel so sign can be easily seen per Rule 605.

COGCC Decision:

COGCC  
Representative:

2 CA# 157559

Corrective Action: MAINTAIN VEGETATION PER RULE606.

Date: 12/04/2021

Response: CA COMPLETED

Date of Completion: 01/11/2022

Operator  
Comment: Maintained Vegetation to comply with Rule 606.

COGCC Decision:

COGCC  
Representative:

3 CA# 157560

Corrective Action: Install or repair required BMPs per Rule 1002. SERIES RULES.

Date: 12/04/2021

Response: CA COMPLETED

Date of Completion: 12/01/2021

Operator  
Comment: Installed and repaired required BMP's per Rule 1002.

COGCC Decision:

COGCC  
Representative:

4 CA# 157561

Corrective Action: IMMEDIATELY LOWER FLUID LEVEL IN PIT AND MAINTAIN FLUID LEVEL A MINIMUM OF 2' BELOW GROUND LEVEL PER RULE. 909.c.

Date: 11/05/2021

Response: CA COMPLETED

Date of Completion: 12/01/2021

Operator  
Comment: Lowered level in pit and will maintain fluid level per Rule 909.c.

COGCC Decision:

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Please find the attached Photo's

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Susan Wolfram

Signed: \_\_\_\_\_

Title: Sr. Safety Coordinator

Date: 1/13/2022 6:45:11 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**    **Description**

402926378	LPGC 32-32
-----------	------------

Total Attach: 1 Files