

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402930971

Date Received:
01/19/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10518

Name of Operator: CONFLUENCE DJ LLC

Address: 1001 17TH STREET #1250

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Brittany Rothe</u>	<u>303-994-3064</u>	<u>brothe@confluencelp.com</u>
<u>Bob Weitzel</u>	<u>970-481-8730</u>	<u>rweitzel@confluencelp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 699105014

Inspection Date: 01/10/2022

FIR Submit Date: 01/10/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CONFLUENCE DJ LLC

Company Number: 10518

Address: 1001 17TH STREET #1250

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 451960

Location Name: 70 Ranch Number: 10 East County: _____

Qtrqtr: SENE Sec: 10 Twp: 4N Range: 63W Meridian: 6

Latitude: 40.327580 Longitude: -104.416920

FACILITY - API Number: 05-123-00 Facility ID: 451960

Facility Name: 70 Ranch Number: 10 East

Qtrqtr: SENE Sec: 10 Twp: 4N Range: 63W Meridian: 6

Latitude: 40.327580 Longitude: -104.416920

CORRECTIVE ACTIONS:

1 CA# 159095

Corrective Action: "Properly dispose of oily waste in accordance with 905.e."

Date: 01/19/2022

Response: CA COMPLETED

Date of Completion: 01/17/2022

Operator Comment: All oily waste in buckets/barrel was removed and appropriately disposed of. See attached photos for confirmation.

COGCC Decision: _____

COGCC
Representative:

2 CA# 159096

Corrective Action: Comply with Rule 606

Date: 01/19/2022

Response: CA COMPLETED

Date of Completion: 01/17/2022

Operator
Comment:

The subject buckets/barrel have been removed from location. See attached photos for confirmation.

COGCC Decision: _____

COGCC
Representative:

3 CA# 159097

Corrective Action: Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b

Date: 01/19/2022

Response: CA COMPLETED

Date of Completion: 01/17/2022

Operator
Comment:

OOSLAT identification has been applied to all out-of-service lines on the subject location. See attached photos for confirmation.

COGCC Decision: _____

COGCC
Representative:

4 CA# 159098

Corrective Action: "Properly dispose of oily waste in accordance with 905.e."

Date: 01/19/2022

Response: CA COMPLETED

Date of Completion: 01/17/2022

Operator
Comment:

All stained soil around the two subject wellheads has been removed. See attached photos for confirmation.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: We want to apologize for the oil around the wellheads and oily waste in buckets. We had just has some issues with stuffing box rubbers the day before and hadn't cleaned it up yet when the inspection took place. Normally, the oily waste would not be there.

Thanks, please let us know if there are follow-up questions or concerns.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brittany Rothe

Signed: _____

Title: Engineering Manager

Date: 1/19/2022 2:13:33 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402931021	Corrective Action Response Photo #1
402931029	Corrective Action Response Photo #2
402931032	Corrective Action Response Photo #3
402931039	Corrective Action Response Photo #4
402931048	Corrective Action Response Photo #5
402931049	Corrective Action Response Photo #6
402931051	Corrective Action Response Photo #7
402931053	Corrective Action Response Photo #8
402931058	Corrective Action Response Photo #9
402931059	Corrective Action Response Photo #10
402931060	Corrective Action Response Photo #11

Total Attach: 11 Files