

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402945195

Date Received:
02/02/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
O'SHIELDS, CHARLIE	940-682-5030	coshields@ogrisop.com
GEE, GREG	903-987-0353	ggee@ogrisop.com
GIENA WARD	719-220-4041	gward@ogrisop.com
ATWATER, BONNIE	432-755-0212	batwater@ogrisop.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690201883

Inspection Date: 07/29/2021

FIR Submit Date: 07/30/2021

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-4978
VILLAGE

LOCATION - Location ID: 307274

Location Name: APACHE CANYON-634S68W Number: 2SWSW County: LAS ANIMAS

Qtrqtr: SWS Sec: 2 Twp: 34S Range: 68W Meridian: 6
W

Latitude: 37.107810 Longitude: -104.971660

FACILITY - API Number: 05-071- -00 Facility ID: 217348

Facility Name: APACHE CANYON Number: 2-13

Qtrqtr: SWS Sec: 2 Twp: 34S Range: 68W Meridian: 6
W

Latitude: 37.107810 Longitude: -104.971660

CORRECTIVE ACTIONS:

1 CA# 154341

Corrective Action: Conduct maintenance on equipment, cleanup stained material, and review self inspection processes.

Date: 04/09/2021

Response: CA COMPLETED

Date of Completion: 11/08/2021

Operator
Comment:

MAINTENANCE HAS BEEN PERFORMED, THE IMPACTED SOIL NEAR THE LIQUID RING SKID WAS REMOVED AND THE SELF INSPECTION PROCESS HAS BEEN REVIEWED. SEE ATTACHED PHOTO LOG FOR DETAILS.

COGCC Decision: _____

COGCC
Representative:

2 CA# 154342

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 05/07/2021

Response: CA COMPLETED

Date of Completion: 11/03/2021

Operator
Comment:

REQUIRED BMPs HAVE BEEN INSTALLED AND REPAIRED. SEE ATTACHED PHOTO LOG FOR DETAILS.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA WARD

Signed: _____

Title: ENVIRONMENTAL TECH.

Date: 2/2/2022 11:52:39 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402945220	SEE ATTACHED PHOTO LOG FOR DETAILS.
-----------	-------------------------------------

Total Attach: 1 Files