

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402949744

Date Received:
02/07/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

TEP

Phone

970-285-9377

Email

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700703767

Inspection Date: 01/24/2022

FIR Submit Date: 01/25/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 324122

Location Name: CLOUGH-66S94W Number: 27NWNW County: _____

Qtrqr: NWN Sec: 27 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.500669 Longitude: -107.882240

FACILITY - API Number: 05-045-00 Facility ID: 324122

Facility Name: CLOUGH-66S94W Number: 27NWNW

Qtrqr: NWN Sec: 27 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.500669 Longitude: -107.882240

CORRECTIVE ACTIONS:

1 CA# 159353

Corrective Action: Remove debris

Date: 02/04/2022

Response: CA COMPLETED

Date of Completion: 01/26/2022

Operator Comment: Debris has been removed.

COGCC Decision: _____

Date: 03/04/2022

Date of Completion: 01/27/2022

Rule 603.i requires that load lines be plugged. All load lines at this location are plugged. The inspection photo shows a drain line, which do not require a plug per Rule 603.i.

COGCC Decision:

--

Comment:	Both corrective actions have been completed / addressed.
----------	--

Signed:

Date: 2/7/2022 2:05:28 PM

--	--

Page 2 of 2