

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402960416

Date Received:

02/18/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
O'SHIELDS, CHARLIE	940-682-5030	coshields@ogrisop.com
GEE, GREG	903-987-0353	ggee@ogrisop.com
ATWATER, BONNIE	432-755-0212	batwater@ogrisop.com
GIENA WARD	719-220-4041	gward@ogrisop.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690201889

Inspection Date: 07/29/2021

FIR Submit Date: 07/30/2021

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-4978
VILLAGE

LOCATION - Location ID: 308879

Location Name: APACHE CANYON-634S68W Number: 1NENW County: LAS ANIMAS

Qtrqr: NENW Sec: 1 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.120377 Longitude: -104.950426

FACILITY - API Number: 05-071- -00 Facility ID: 284278

Facility Name: APACHE CANYON Number: 1-3

Qtrqr: NENW Sec: 1 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.120377 Longitude: -104.950426

CORRECTIVE ACTIONS:

1 CA# 154344

Corrective Action: Conduct maintenance on equipment, cleanup stained material, and review self inspection processes.

Date: 08/06/2021

Response: CA COMPLETED

Date of Completion: 08/05/2021

Operator Comment: MAINTENANCE HAS BEEN PERFORMED, THE IMPACTED SOIL NEAR THE LIQUID RING COMPRESSOR SKID WAS REMOVED AND THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 154345

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 08/20/2021

Response: CA COMPLETED

Date of Completion: 02/16/2022

Operator Comment: THE MAIN LEASE ROAD WAS SURFACED CROWNED TO ELIMINATE SURFACE EROSION AND CREATE SHEET FLOW. GRAVEL WAS PULLED OUT OF THE BAR DITCH/EDGE OF ROAD BACK ONTO THE ROAD SURFACE. ADDITIONAL GRAVEL WAS INSTALLED TO THE ROADWAY SURFACE FOR STABILIZATION.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA WARD

Signed: _____

Title: ENVIRONMENTAL TECHNICIAN

Date: 2/18/2022 2:31:32 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402960430	PHOTO LOG
-----------	-----------

Total Attach: 1 Files