

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/02/2022

Submitted Date:

03/02/2022

Document Number:

696303994

FIELD INSPECTION FORMLoc ID 430061 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96155

Name of Operator: WHITING OIL & GAS CORPORATION

Address: 1700 LINCOLN STREET SUITE 4700

City: DENVER State: CO Zip: 80290

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, CODY		ctrutt@fundareresources.com	PRINCIPAL AGENT
Linhardt, Cliff		clinhardt@fundareresources.com	DESIGNATED AGENT
Smith, Sydney		ssmith@fundareresources.com	Regulatory
Kraich, Adam		adam.kraich@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430062	WELL	PR	12/16/2012	OW	123-36029	Razor 14-1143H	PR

General Comment:

Inspected Facilities

Facility ID: 430062 Type: WELL API Number: 123-36029 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Workover

Comment: Workover Rig was observed Rigging up on Location at approximately 13:55 on 03.02.2022 - No Form 42 for Move In Rig Up is on File per Rule 405.e. (2) - (3)

Corrective Action: Submit Form 42 per Rule 405.e (2) - (3) BEFORE Workover Rig shows up

Date: 03/02/2022

COGCC Comments

Comment

User

Date

On Wednesday 03/03/2022 at approximately 13:55, I, Inspector Erica Petrie, conducted a Field Inspection at FUNDARE RESOURCES OPERATING COMPANY LLC, Razor 14-1143H, Location #430061 in Weld County, Colorado.

petrie

03/02/2022

While there, I observed Production Operations

During this Inspection the following possible compliance issues were observed:

Workover Rig was observed Rigging up on Location at approximately 13:55 on 03.02.2022 - No Form 42 for Move In Rig Up is on File per Rule 405.e. (2) - (3). Submit Form 42 per Rule 405.e (2) - (3) BEFORE Workover Rig shows up. Corrective Action Date 03.02.2022

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402971827	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5680229
696303995	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5680228