

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/17/2022

Submitted Date:

03/18/2022

Document Number:

700703983

FIELD INSPECTION FORM

Loc ID 335342 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256100	WELL	PR	09/20/1999	GW	045-07430	CLOUGH RMV 210-20	PR
260584	WELL	PR	07/10/2001	GW	045-07875	CLOUGH RWF 434-20	PR

General Comment:

[COGCC Inspection Report Summary](#)
On Thursday 3/17/2022 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RMV 210-20, at Location # 335342 in Garfield county Colorado.
Any Corrective Actions from previous Inspections that have not been addressed are still applicable.
While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

During this inspection the following possible compliance issues were observed:
1. Location shows some signs of lack of stabilization/ compaction/ degrading.
2. One dead man is not marked.

Refer to photograph of observed compliance issue.
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	_____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Deadman # & Marked	# 5	Comment: 1 deadman is not marked	Corrective Action: Mark or remove deadman	Date: 04/22/2022	
Type: Bradenhead	# 2	Comment:	Corrective Action:	Date:	
Type: Plunger Lift	# 2	Comment:	Corrective Action:	Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 256100 Type: WELL API Number: 045-07430 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Facility ID: 260584 Type: WELL API Number: 045-07875 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					

Comment: [1. Location shows some signs of lack of stabilization/ compaction/ degrading.](#)

Corrective Action: **Install or repair required BMPs**

Date: 05/20/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402989112	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5698123
700703989	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5698117