

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403018708

Date Received:
04/19/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Koehler, Bob		regulatory@foundationenergy.com
		bob.koehler@state.co.us
		dnr_cogccengineering@state.co.us
Leonard, Mike		mike.leonard@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 691200319
Inspection Date: 08/01/2018 FIR Submit Date: 08/01/2018 FIR Status: _____

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC Company Number: 10112
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 418908

Location Name: WICKSTROM Number: 6-12 County: _____
Qtrqr: NWS Sec: 6 Twp: 7N Range: 59W Meridian: 6
W
Latitude: 40.602620 Longitude: -104.028730

FACILITY - API Number: 05-123-00 Facility ID: 418908

Facility Name: WICKSTROM Number: 6-12
Qtrqr: NWS Sec: 6 Twp: 7N Range: 59W Meridian: 6
W
Latitude: 40.602620 Longitude: -104.028730

CORRECTIVE ACTIONS:

1 CA# 117793

Corrective Action: Comply with Rule 604.c.(2)Q.

Date: 08/16/2018

Response: CA COMPLETED

Date of Completion: 10/02/2018

Operator Comment: FIR Doc #691200541 states that this corrective action item was addressed, all anchors were properly marked. Inspection date is entered as date of completion.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 117794

Corrective Action: Comply with Rule 603.f .

Date: 11/27/2017

Response: CA COMPLETED

Date of Completion: 10/02/2018

Operator Comment: FIR Doc #691200541 stated that this corrective action was addressed, the unused equipment SW of the wellhead was removed. Inspection date is entered as date of completion.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 117795

Corrective Action: Comply with rule 605.d.

Date: 09/03/2018

Response: CA COMPLETED

Date of Completion: 10/02/2018

Operator Comment: FIR Doc #691200541 stated that this corrective action was addressed, bradenhead was plumbed to surface. Inspection date is entered as date of completion.

COGCC Decision: _____

COGCC Representative: _____

4 CA# 117801

Corrective Action: Comply with Rule 326

Date: 08/13/2018

Response: CA COMPLETED

Date of Completion: 10/02/2018

Operator Comment: MIT was conducted 10/2/2018; Form 21 Doc #401781099.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: The follow up inspection (Doc #691200541) that occurred on 10/2/2018 noted that these corrective action items had been addressed. MIT was conducted in October 2018 and the Form 21 Doc # is provided in the CA response section of this FIRR.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Afton Iiams

Signed: _____

Title: HSE/Regulatory Technician

Date: 4/19/2022 12:16:05 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files