

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/20/2022

Submitted Date:

04/20/2022

Document Number:

699503885

**FIELD INSPECTION FORM**

Loc ID 318925 Inspector Name: MEDINA, JUSTIN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	<a href="#">all inspections.</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242493	WELL	PR	01/01/2022	OW	123-10284	GEORGE R NORDEN UNIT 1	PR

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type OTHER

Comment: : Spill that was discovered from Inspection Document # 699502721,699503230 has not been addressed since discovery on 4/29/21. Free standing fluids were addressed but flowline in questions has not been repaired and area of effect has not been addressed by KPK.

Corrective Action: : Comply with 912 a

Date: 06/11/2021

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type WELLHEAD

Comment: fabricated fencing

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date:

Type: Bradenhead # 1

Comment: plumbed to surface

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: plunger automation

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 242493 Type: WELL API Number: 123-10284 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/13/2021 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0  
 Comment: New bradenhead test will be needed this month.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On 4/19/2022 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- George R Norden Unit 1                      Company Name- KPK                      API- 05-123-10284                      In Weld County Colorado.                      While there, I observed SI well                      This is a follow up inspection from document # 699503230 699502721 Corrective Actions are Delinquent                      During this inspection the following possible compliance issues were observed:                      Spill that was discovered from Inspection Document # 699502721,699503230 has not been addressed since discovery on 4/29/21. Free standing fluids were addressed but flowline in questions has not been repaired and area of effect has not been addressed by KPK                      Comply with 912 a 6/11/21                      Annual bradenhead test will need to be performed this month.                      .A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This inspection does not nullify any orders or NOAV from the COGCC.                      This is a summary of inspection report.</p>	medinaj	04/20/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403022460	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5729303">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5729303</a>
699503886	inspection pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5729294">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5729294</a>