



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	not secured. could blow away.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate	Date:	
Corrective Action:			

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment in multiple spots, needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606 Submit photos with FIRR	Date:	05/06/2022
Type	OTHER		
Comment:	Stained soil around well needs to be reamoved. See attached photo.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e." Submit photos with FIRR	Date:	05/06/2022

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	Metal Grate		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 428523 Type: WELL API Number: 123-35394 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Pump Jack currently down

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 08/13/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On Wednesday 4/27/22 at approximately 0954hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Park T-P-4HZ of Civitas, at API # 05-123-35394 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      Stained soil around well needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 5/6/22                      Unused equipment in multiple spots, needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/6/22                      See attached photos.                      Submit pictures on FIRR.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	burnsa	04/27/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699105304	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5736710">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5736710</a>