

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/25/2022

Submitted Date:

04/27/2022

Document Number:

690202828**FIELD INSPECTION FORM**Loc ID 324802 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 16520Name of Operator: CHEMCO INCAddress: 6970 SOUTH HOLLY CIR STE 206City: CENTENNIAL State: CO Zip: 80112**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neher, Gray		gh.neher@chemco-og.com	
Neher, Morgan		morgan@chemco-og.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
150396	UIC DISPOSAL	AC	01/05/1996		-	WEAR*H C 3-1	RI

General Comment:

This a follow up inspection was performed at the Wear #3-1 Tank Battery Site.
See attached photos and additional details within this report.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Sign reinstalled.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Leak at tank repaired.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	There is a barrel onsite that contains burnt ashes which indicates burning onsite which was also observed in a previous inspection. No trash, waste, rubbish, or other materials will be burned or buried at an Oil and Gas Location.		
Corrective Action:		Date:	
Type	STORAGE OF SUPL		
Comment:	There is various unused unnecessary equipment/supplies being stored at the location. All supplies not necessary for use on the location is prohibited.		
Corrective Action:	Comply with Rule 606	Date:	01/28/2022
Type	OTHER		
Comment:	The electric utility box was closed and wired. The electric line remains exposed on the ground and needs to be protected.		
Corrective Action:	Comply with 602 SAFETY REQUIREMENTS.	Date:	01/14/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	Truck Loadout			
Comment:	There is still oily waste at the load out area that needs to be cleaned up.			
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.			Date:

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Inspector Name: COSTA, RYAN

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	The berms around the tank battery has been built up better to contain a spill.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690202829	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5737037