

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/25/2022

Submitted Date:

05/09/2022

Document Number:

699700304

**FIELD INSPECTION FORM**Loc ID 315979 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 3104

Name of Operator: ANSCHUTZ EXPLORATION CORP

Address: 555 17TH ST STE 2400

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Herbison, Lacy	(303) 299-1422	lacy.herbison@gmail.com	Regulatory Analyst
Organ, Lindsey		lindsey.organ@aec-denver.com	Compliance Specialist

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269711	PIT	AC	10/08/2003		-	PRF C-1W	AC

**General Comment:**

On April 25, 2022, COGCC Environmental Staff (John Heil) conducted an environmental field inspection of ANSCHUTZ EXPLORATION CORP (ANSCHUTZ operator #3104) Pinyon Ridge Federal C1-W Location ID 315979 to examine Spill/Release ID 481972 that was reported by ANSCHUTZ on March 31, 2022.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Sign not updated to reflect current operator.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	05/11/2022

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: See Spill/Release ID 481972 for more information. 4/25/2022 COGCC staff observed potentially impacted material within the tank battery secondary containment structure (where the spill/release occurred) as well as various locations on the Pinyon Ridge Federal C1-W location. There were multiple areas on the exterior of the tank battery secondary containment structure where fluids had escaped the secondary containment structure and migrated across the location. The potentially impacted material had a strong hydrocarbon odor and produced a sheen when in contact with what appeared to be storm water within the secondary containment structure. The potential impacts were observed on the eastern and northeastern portions of the location and a residual impact ring was observed on the northeast corner of the tank battery secondary containment structure. See attached Photo Log for details.

Corrective Action: Control and contain spills/releases and immediately clean up per Rule 912.a. Operator shall submit a Form 27 Per Rule 913.c.(8).

Date: 05/23/2022

Reportable: YES

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat

Long

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: \_\_\_\_\_ Lined: NO Pit ID: 269711 Lat: 40.212478 Long: -108.276279

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition:

Comment: Appears to be an earthen pit

Corrective Action

Operator shall provide the status of Pit ID 269711. If the pit is no longer in use, the operator shall close the pit in accordance with Rule 911 and Rule 913. CA date is from 4/5/2022 Inspection Doc #699700298.

Date: 05/11/2022**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective

Date:

**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective

Date:

Permit:	Facility ID	Permit Num	Expiration Date
	269711	1202517	
	269711	1202517	

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700307	20220425 Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5748582">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5748582</a>