

Richardson E1

COGCC Inspection Doc # 693903870

Hydroseed cut bank (this was done back in December)

Re-establish drainage on west side of location to direct water to rock run out along road

CA Complete 03/31/2022



