

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/19/2022

Submitted Date:

05/20/2022

Document Number:

701103131**FIELD INSPECTION FORM**Loc ID 314347 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 77900Name of Operator: SHAWNEE OIL DEVELOPMENT CO INCAddress: P O BOX 300City: KEVIN State: MT Zip: 59454**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hawkins, Jim	406-873-5277	jhawkins@bresnan.net	
, Engineering		dnr_cogccengineering@state.co.us	All engineering

**General Comment:**

COGCC Follow Up Inspection Report Summary

Follow up to 05/03/2022 inspection # 701103034

Corrected action item

• Access gained by gate combination from Jim Hawkins

During this inspection the following compliance issues were observed:

- Braden access installed. Gap in flange may not provide isolation.
- Markers not brightly colored. Deadmen anchors hidden by grown up brush.
- Location not kept free of weeds.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access gained by gate combination from Jim Hawkins		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911	Date:	
Corrective Action:			

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Location not kept free of weeds.		
Corrective Action:	Comply with Rule 606	Date:	06/04/2022

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Braden access installed. Gap in flange may not provide isolation.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)	Date:	06/04/2022
Type: Deadman # & Marked	# 4		
Comment:	Markers not brightly colored. Deadmen anchors hidden by grown up brush.		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	06/04/2022

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103132	Inspection 701103131 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5759266">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5759266</a>