

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403054576

Date Received:
05/19/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>GIENA WARD</u>	<u>719-220-4041</u>	<u>gward@ogrisop.com</u>
<u>ATWATER, BONNIE</u>	<u>432-755-0212</u>	<u>batwater@ogrisop.com</u>
<u>BACA, DAVID</u>	<u>719-859-4066</u>	<u>dbaca@ogrisop.com</u>
<u>O'SHIELDS, CHARLIE</u>	<u>940-682-5030</u>	<u>coshields@ogrisop.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690201359

Inspection Date: 04/01/2021

FIR Submit Date: 04/02/2021

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309392

Location Name: APACHE CANYON-634S68W Number: 1NWSW County: LAS ANIMAS

Qtrqtr: NWS Sec: 1 Twp: 34S Range: 68W Meridian: 6
W

Latitude: 37.111001 Longitude: -104.955502

FACILITY - API Number: 05-071- -00 Facility ID: 294301

Facility Name: APACHE CANYON Number: 1-12

Qtrqtr: NWS Sec: 1 Twp: 34S Range: 68W Meridian: 6
W

Latitude: 37.111001 Longitude: -104.955502

CORRECTIVE ACTIONS:

1 ☒ CA# 148046

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 05/14/2021

Response: CA COMPLETED

Date of Completion: 05/18/2022

Operator
Comment:

THE EROSION OF THE FILL SLOPE ON THE UPPER MAIN LEASE ROAD OF ALAMOSITO WAS REPAIRED. THE DIVERSION DITCH ALONG THE ENTIRE ACCESS HAS BEEN CLEANED OF SEDIMENT AND REDIFINED TO DIRECT STORMWATER TO CULVERTS. THE FILL SLOPE HAS ALSO BEEN SEEDED USING AN APPROVED CPW SEED MIX TO PROMOTE THE ESTABLISHMENT OF VEGETATION. SEE PHOTO LOG FOR ADDITIONAL DETAILS.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 148047

Corrective Action: Net or fence pit to prevent access per rule 909.f.

Date: 04/16/2021

Response: CA COMPLETED

Date of Completion: 08/05/2021

Operator
Comment:

THE ELECTRIC FENCE AROUND THE PIT WAS REPAIRED.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA WARD

Signed: _____

Title: SR. ENVIRONMENTAL TECH.

Date: 5/19/2022 12:17:54 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403054576	FIR RESOLUTION SUBMITTED
403054610	PHOTO LOG

Total Attach: 2 Files