

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403032716

Date Received:

04/29/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Romana Cowden

Phone

720-951-5895

Email

cogcc.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202448

Inspection Date: 03/09/2021

FIR Submit Date: 03/11/2021

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335822

Location Name: N. PARACHUTE-65S95W Number: 28NWNW County: _____

Qtrqr: NWN Sec: 28 Twp: 5S Range: 95W Meridian: 6
W

Latitude: 39.588606 Longitude: -108.065458

FACILITY - API Number: 05-045- -00 Facility ID: 335822

Facility Name: N. PARACHUTE-65S95W Number: 28NWNW

Qtrqr: NWN Sec: 28 Twp: 5S Range: 95W Meridian: 6
W

Latitude: 39.588606 Longitude: -108.065458

CORRECTIVE ACTIONS:

1 ☒ CA# 147288

Corrective Action: Conduct additional reclamation in accordance with COGCC 1000 series rules. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed.

Date: 04/30/2021

Response: CA COMPLETED

Date of Completion: 07/29/2021

Slopes were seeded and mulched to address vegetation on the slope in 2021. Additional maintenance

Operator Comment: preformed in 2022: Additional reclamation of vertical cut on Norther diversion ditch, redefining diversion ditch, and installing checks and armoring. Continued to reseeded the disturbed areas, apply fertilizer, soil amendments, and hydro mulch the disturbed areas.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 4/29/2022 11:28:40 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403032716	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files