



Overview of WC15, Location ID 314513 - northern and southern portion





Secondary containment BMP was removed from location.



Area was repaired and waddles were repaired or replaced to control sediment

